

Update Record476

215061



GENERAL MESSAGE

TO (name): Chris Jimenez, Laura Ca	POSITION: COM Deputy IC	<input type="checkbox"/>
	LOCATION: R2 REOC	<input type="checkbox"/>
FROM (name): Francesco Maimone	POSITION: PLAN Resource Unit Stal	<input type="checkbox"/>
	LOCATION: R2 REOC	<input type="checkbox"/>
SUBJECT: Request for Facility Follc	DATE: 2012/11/04 (YYYY/MM/DD) <input type="checkbox"/>	TIME: 17:18 (HH:MM)

MESSAGE:

Please see below for follow-up site visits based on reported spills. FM is awaiting contact information from Tabayoyong for USCG coordination. An EPA presenace, even for a brief visit, is recommended for each facility.

Motiva Sewaren- The facility's spill has impacted other facilities, at least as far away as Kinder Morgan Perth Amboy (approximately 1.5 miles away). USCG and NJDEP has been involved, but it would be good to get someone on the ground over there. Contact person: Kevin Rizzuto@motivaent.com; 262-348-4208. The proposed group should check-in with Motiva and get an assessment on how well the ICS structure is going. Neighboring facilities (Kinder Morgan Perth Amboy) have deployed their boom, but these facilities need their boom in case they have spills themselves. The concern is that Motiva Sewaren is not making enough progress. USCG has been here. Priority Level A because of potential of oil migration.

Kinder Morgan Carteret Terminal- Check-up on status of spill clean-up of 10,000 gallons biodiesel and 225 gallon red dye diesel. The USCG has been here. Priority Level B (bc issue might be resolved at this point). This facility also had NJPDES concerns regarding draining their dikes.

Phillips 66 Bayway- Check-up on status of cleanup. USCG has been here. Priority Level B bc it appears that most of the oil had been contained onsite in Morses Creek.

The same crew can go to all three facilities above in one day to get a status report, show presence, and assist if necessary. These efforts should be coordinated with the USCG. I can call each facility above and find out who their

SUBMITTED BY (name): Francesco Maimone	POSITION: PLAN Resource Unit Stal <input type="checkbox"/>
---	---

REPLY:

Completed: ☒ Yes ☐ No

Ongoing assistance being provided to the Coast Guard as needed.

DATE: 2012/11/09 (YYYY/MM/DD) <input type="checkbox"/>	TIME: 1530	SIGNATURE/POSTITION: Resources
--	-------------------	---------------------------------------

ICS 213

NFES 1336

Update Record476

GENERAL MESSAGE		
TO (name): Chris Jimenez, Laura Ca	POSITION: COM Deputy IC	<input type="checkbox"/>
	LOCATION: R2 REOC	<input type="checkbox"/>
FROM (name): Francesco Maimone	POSITION: PLAN Resource Unit Sta	<input type="checkbox"/>
	LOCATION: R2 REOC	<input type="checkbox"/>
SUBJECT: Request for Facility Folc	DATE: 2012/11/04 (YYYY/MM/DD) <input type="checkbox"/>	TIME: 17:18 (HH:MM)
MESSAGE:		
<p>Please see below for follow-up site visits based on reported spills. FM is awaiting contact information from Tabayoyong for USCG coordination. An EPA presenrce, even for a brief visit, is recommended for each facility.</p> <p>Motiva Sewaren- The facility's spill has impacted other facilities, at least as far away as Kinder Morgan Perth Amboy (approximately 1.5 miles away). USCG and NJDEP has been involved, but it would be good to get someone on the ground over there. Contact person: Kevin Rizzuto@motivaent.com; 262-348-4208. The proposed group should check-in with Motiva and get an assessment on how well the ICS structure is going. Neighboring facilities (Kinder Morgan Perth Amboy) have deployed their boom, but these facilities need their boom in case they have spills themselves. The concern is that Motiva Sewaren is not making enough progress. USCG has been here. Priority Level A because of potential of oil migration.</p> <p>Kinder Morgan Carteret Terminal- Check-up on status of spill clean-up of 10,000 gallons biodiesel and 225 gallon red dye diesel. The USCG has been here. Priority Level B (bc issue might be resolved at this point). This facility also had NJPDES concerns regarding draining their dikes.</p> <p>Phillips 66 Bayway- Check-up on status of cleanup. USCG has been here. Priority Level B bc it appears that most of the oil had been contained onsite in Morses Creek.</p> <p>The same crew can go to all three facilities above in one day to get a status report, show presence, and assist if necessary. These efforts should be coordinated with the USCG. I can call each facility above and find out who their</p>		
SUBMITTED BY (name): Francesco Maimone	POSITION: PLAN Resource Unit Sta <input type="checkbox"/>	
REPLY:		
Completed: <input type="radio"/> Yes <input type="radio"/> No		
<p>Ongoing assistance being provided to the Coast Guard as needed.</p>		
DATE: (YYYY/MM/DD) <input type="checkbox"/>	TIME: <input type="checkbox"/>	SIGNATURE/POSTITION: <input type="text"/>

ICS 213

NFES 1336